UNCLASSIFIED

AD 425071

DEFENSE DOCUMENTATION CENTER

FOR

SCIENTIFIC AND TECHNICAL INFORMATION

CAMERON STATION, ALEXANDRIA, VIRGINIA



UNCLASSIFIED

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

Doc allu: Accuser Dir

CATALOGED BY DDC
AS AD No.

120227

425071



MCDONNELL

DATE	10	December	1963
REVISED			

EVALUATION OF DRY

FILM LUBRICANTS

ON

ALUMINUM AND MAGNESIUM

REPORT A262 SERIAL NO. 12

MCDONNELL

This report was prepared under Contract Number AF33(657)-11215 and BPSN: 63-6899-7381-738103. Additional information pertaining to any data contained herein may be obtained from the Directorate of Materials and Processes (ASRCEM-1), Aeronautical Systems Division, Air Force Systems Command, United States Air Force, Wright-Patterson Air Force Base, Ohio, or McDonnell Aircraft Corporation, St. Louis, Missouri

INDEX
CODE (Lub-3)(IV-e)(V-a,e)

DATE 20 December 1962
REVISED Rev. A (k-10-63)

ST. LOUIS, MISSOURI

PAGE	l
FAGE	
REPORT	A 262

REVISED _____

FINAL REPORT

IABORATORY: Structures

EVALUATION OF DRY FILM LUBRICANTS ON ALUMINUM AND MAGNESIUM

ABSTRACT

Vendors' literature has recommended the application of dry film lubricants to various aluminum and magnesium alloys. In order to evaluate these recommendations, combinations of several dry film lubricants applied to representative aluminum and magnesium alloys with various surface preparation procedures were tested.

Of the combinations tested, the optimum combination of surface pretreatment and dry film lubricant in the case of 7075-T6 aluminum alloy was found to be Electrofilm 5396 lubricant applied to a hard coated surface. When testing HK31A magnesium alloy, the optimum combination was that of Electrofilm 5396 applied to a surface pretreated with a Dow 17 Type I coating, followed by Everlube 620 lubricant applied to the same pretreated surface.

Approved by Williams Iab Approved by Checker Senior Engineer - Iab

Approved by Chief, Structures Iab

Approved by Iab Project Engineer

DATE 20 December 1962
REVISED (Rev. A.) 4-10-63

ST. LOUIS, MISSOURI

.PAGE _	2
REPORT	A262

REVISED _____

LABORATORY REPORT

FINAL REPORT

1. INTRODUCTION

A need has developed for test data concerning the performance to be expected from dry film lubricants when applied to aluminum and magnesium alloys. Recommendations for these applications have appeared in some recent vendors' literature. Tests were conducted at room temperature and at 250F with 3 dry film lubricants applied to an aluminum and a magnesium alloy, each with various surface preparations.

These tests were performed by the Structures Laboratory of McDonnell Aircraft Corporation during the period 5 March through 11 September 1962.

2. DESCRIPTION OF TEST ARTICLES

The test cups and riders were fabricated to the configuration shown in Figures 1 and 2 on page 8. Nine of the test cups were made of 7075-T6 aluminum alloy and 6 of HK51A magnesium alloy. The riders were of 52100 steel (Ro58), and were drilled to provide a thermocouple well to be used in elevated temperature testing.

Three of the aluminum alloy test cups were subjected to each of the following surface preparation methods: Hard coat 0.002-inch thick per PS 13208, alodine per PS 13209, and anodize per PS 13201. Three of the magnesium alloy cups were surface-conditioned by each of the following methods: Dow 17 coating, Type I, per PS 13217, and HAE Type II coating performed by an outside vendor.

The dry film lubricants included in the tests, Molykote X-106, Electrofilm 5396, and Everlube 620, were applied to the test cups by spraying. Micrometer measurements were conducted before and after spraying to assure uniform lubricant thickness.

Table 1 on page 5 summarizes the surface preparation and lubricant applied to each of the test cups.

3. TEST PROCEDURE

All tests were conducted on a McMillan wear tester shown in Figure 3 on page 9, equipped with a heating element and pyrometer for elevated temperature testing. A cutoff switch, activated by the input of a strain gage, was employed to stop the test when the coefficient of friction reached 0.2. The strain gages were attached to the oscillating linkage arm, as shown in Figure 4 on page 10, and were calibrated to relate the strain in the linkage arm to a coefficient of friction of 0.2.

-A

-A

MAC 231, TREAT AND FIL

DATE 20 December 1962

REVISED Rev. A (4-10-63)

ST. LOUIS, MISSOURI

PAGE	3
1 AUL	A262
REPORT	A202
1/LI VIVI	

REVISED _____

FINAL REPORT

3. TEST PROCEDURE (CONTINUED)

If this point was not attained, the test was discontinued after 50 hours.

The test cups were rotated with an oscillating motion through an arc of approximately \$5°. This resulted in a test length of about 0.75 inch and allowed 4 tests per cup, 2 at room temperature followed by 2 at 250F. The position of the test cup relative to the rider is shown in Figure 5 on page 11.

The normal load applied to the test surface was calculated from the weight applied to the load pan, plus that of the pan and linkage arm, reacting through a linkage arm ratio of 29.5. Normal loads of 99 sounds were applied to the magnesium alloy surfaces, and of 187.5 pounds to the aluminum alloy test surfaces. In each case, the load was applied in increments to prevent premature failure because of possible damage to the test surface caused by sudden loading. The timer was started after loading was completed, and subsequent inspections performed to assure even contact between the test cups and riders.

4. TEST RESULTS

The oscillatory motion was applied at a rate of 195 cycles per minute; after measuring the time to failure, the number of cycles sustained before failure was calculated. In several cases, failure occurred during loading and the cycles to failure values was taken as zero.

The test results are tabulated for the aluminum alloy, 7075-T6 and the magnesium alloy, HK31A, in Tables 2 and 3 on pages 6 and 7, respectively.

5. DISCUSSION OF TEST RESULTS

Of the various combinations of base metal alloy, surface preparation, and dry film lubricant tested, either at room temperature or at 250F, none approached the 50 hour maximum test period. Considerable scatter in the test results was encountered; frequently one test condition would yield comparatively good results and an identical test would result in failure before the load was completely applied. The photomacrographs presented in Figures 6 through 33 on pages 12 through 39 show the surfaces of each cup section at approximately 4X magnification after test. The results of Test No. 28 were discarded because the contact area was approximately twice as long as those of the other tests.

DATE 20 December 1962

REVISED Rev. A (4-10-63)

ST. LOUIS, MISSOURI

PAGE	44
REPORT	A262

REVISED _____

LABORATORY REPORT

FINAL REPORT

6. CONCLUSION

Of the combinations of dry film lubricant and surface pretreatment tested with 7075-T6 aluminum alloy, the optimum combination of surface pretreatment and dry film lubricant application was that of Electrofilm 5396 applied to a surface hard coated in accord with PS 13208. The next 2 most successful combinations were Everlube 620 applied to a hard coated aluminum surface, followed by Electrofilm 5396 applied to a surface alodined per PS 13209.

In testing HK51A magnesium alloy cups, the optimum surface preparation dry film lubricant combination was found to be Electrofilm 5396 lubricant applied to a Dow 17 Type I surface, followed by Everlube 620 applied to the magnesium alloy of the same surface preparation.

MAT 2310 (SE2 1 AU) 614

L۵

DATE _____

REVISED _____

ST. LOUIS, MISSOURI

PAGE 5 REPORT A262

LABORATORY REPORT

REVISED ..

TABLE 1 PREPARATION OF TEST CUPS

DRY FILM LUBRICANT	EVERLUBE 620	MOLYKOTE X-106	ELECTROFILM 5396	EVERLUBE 620	MOLYKOTE X-106	ELECTROFILM 5396	EVERLUBE 620	MOLYHOTE X-106	ELECTROFILM 5396	EVERLUBE 620	MOLYHOTE X-106	ELECTROFILMS396	EVERLUBE 620	MOLYKOTE X-106	ELECTROFILM 5396
PRE- TREAT	ALODINE		"	ANOD/ZE	``	;	HARD COAT	:	"	71 MOO	:	;	HAE TYPE II	:	•
MATERIAL	ALUMINUM	11	"	111	"	"	"	=	,	MAGNESIUM	71	:	÷	÷	*
TEST		N	Ŋ	4	5	V	\	ω	თ	0/	//	12	73	4/	15

ST. LOUIS, MISSOURI

PAGE	6
REPORT_	A262

REVISED _____

Test Cup	Test No.	Surface Pretreatment	Dryfilm Lubricant Applied	Test Temp.		Cycles to Failure
1	1 2 3	alodine	Everlube 620	R.T. R.T. 250 250	0.0 2.0 1.3 4.0	0 23,160 15,054 46,320
2	3 4 5 6 7 8		Molykote X-106	R.T. R.T. 250 250	0.0 0.0 0.0	0 0
3	9 10 11 12		Electrofilm 5396	R.T. 250 250	3.0 1.5 3.0 1.1	34,740 15,054 34,740 12,738
1	13 14 15 16	Anodize	Everlube 620	R.T. R.T. 250 250	2.2 2.9 13.6 0.0	25,476 33,582 157,468
5	17 18 19 20		Molykote X-106	R.T. 250 250	0.0	0 0 0
6	21 22 23		Electrofilm 5396	R.T. R.T. 250 250	2.0 3.0 0.0 0.0	23,160 34,740 0
† 7 	24 25 26 27	Hardcoat	Everlube 620	R.T. R.T. 250 250	5.9 5.4 5.9 28.4	68,322 62,532 68,322 328,872
¥ 8 	28 29 30 31		Molykote X-106	R.T. R.T. 250	1.0 1.2 1.3	11,580 13,896 15,054
9	32 33 34 35		Electrofilm 5396	R.T. R.T. 250 250	11.6 10.3 11.3 11.2	134,326 119,274 130,854 126,696

ST. LOUIS, MISSOURI

PAGE	7
REPORT	A262

REVISED BOT. A (4-10-65)

REVISED _____

	TABLE 3 - MACRIESIUM TEST CUPS									
Test Cup	Test	Surface Pretreatment	Dryfilm Lubricant		Time to Failure (hr.)	Cycles to Failure				
10	1 2 3 4 5	Dow 17 type I	Everlube 620	R.T. R.T. 250 250	18.3 0.6 13.4 6.4	211,914 6,948 155,172 74,112				
12	6 7 8 9		Electrofilm 5396	R.T. 250 250 R.T.	1.5 0.0 0.1 1.3 14.5	17,370 0 1,158 15,054 167,910				
13	10 11 12 13 14	HAE type II	Everlube 620	R.T. 250 250 R.T.	3.6 16.4 15.2 0.1	41,688 189,912 176,016 1,158				
14	15 16 17 18		Molykote X-106	R.T. 250 250 R.T. R.T.	0.0 0.0 0.0 0.0	0 0				
15	19 20 21 22		Electrofilm 5396	250 250 R.T. R.T.	0.3 0.1 7.9 1.4	3,474 1,158 91,482 1,621				
	23 24	+		250 250	6.1	70,638 2,316				

ST. LOUIS, MISSOUR

PAGE ______ 8
REPORT _____ A262


17°±15'

0.350 ±0.005

DATE _____

REVISED _____

FIGURE I




TEST CUP CONFIGURATION

NOTES:

I. EXCEPT AS NOTED IN ∇ SYMBOL, HOLD SURFACE FINISH TO 63 RMS MICROINCHES.

CONCENTRICITY OF TAPERED I.D. TO Q.D. TO BE WITHIN 0.0003 T.I.R.

FIGURE 2



TEST RIDER CONFIGURATION

NOTES:

I. TEST RIDER MATERIAL TO BE 52100 STEEL (Rc 30).

/ 3 area / 11 / 190 are

ST. COMS, MISSOURI


LABORATORY REPORT

PAGE 9 REPORT A262

FIRAL REPORT

FIGURE 5 - MC MILLAN DRY FILM LUBRICANT TEST BETUP

D4E-264658



D4E-25 5656


PAGE 10 REPORT A262

LABORATORY REPORT

D4E-264659

FINAL REPORT

FIGURE 4 - STRAIN GAGED INDICATING ARM




D4E-254609

MCDONNELL St. 17 ds, MISS 76/RE

D4E=264660

LABORATORY REPORT



FINAL REPORT

FIGURE 5 - MOUNTED TEST CUPS SHOWING WORK SURFACES



D4E-255655

ST. LOUIS, MISSOURI

REPORT A262

FINAL REPORT

#EVISED

()

LABORATORY REPORT

FIGURE 6



M10528 No. 2

M10527 No. 1

Test Cup 1
Alodine - Everlube 620

()





M10538 No. 3



M10537

Alodine - Everlube 620

DATE

MODONNELL

ST. LOUIS, MISSOURI

TYRONGORE MILENE

PAGE 14 NEPORT A262

FINAL REPORT

FIGURE 8



M1.0509 No. 5



M1.0506

No. 6

Test Cup 2 Alodine - Molykote X-106

ST. LOUIS, MISSOURI

REPORT A262

REVISED DER-OCHECH

()


LABORATORY REPORT

FINAL REPORT

FIGURE 9



M10505 No. 7



M10507

No. 8

Test Cup 2
Alcdine - Molykote X-106

LABORATORY REPORT


FINAL REPORT

FIGURE 10



REVISED __D.Z-264665_

M10534 **50.** 9



M10536 No. 10

Test Cup 3

Alodine - Electrofilm 5396

ST. LOUIS, MISSOURI

REVISED D4E-264666

LABORATORY REPORT

ME 17 NEPONT A262

FINAL REPORT

FIGURE 11



M10929 No. 11



M10535 No. 13

Test Cup 3
Alodine - Electrofilm >3%

MODONNEL

ME-964667


MAII 18 MAINT 1862

YIMAL REPORT

710th 12



M1.0532 No. 13



M10533 No. 14

Test Cup 4 Anodise - Everlube 620

O

MODONNELL


ST. LOUIS, MISSOURI

LABORABURY ERPORT

NEW AREA

FINAL REPORT

FIGURE 13.



REVISED DAE-264668

mary na. 1,



M10530 No. 16

Test Cup 4 Anodize - Everlube 620 MODONNELL

ST. LOUIS, MISSOSTI

LABORATIONY REPORT

REPORT A262

PINAL REPORT


FIGURE 14



()

м10514 и

No. 17



M10512

No. 18

Test Cup 5
Anodize - Molykote X-106

Test Cup 5
Anodize - Holykote X-10s

N10510

M10511


No. 19

FINAL REPORT

DAB-246671


REVISED .

FIGURE 16



MI.0438

No. 21



M10440 No. 22

Test Cup 6 Anodize - Electrofilm 53%

ST. LOUIS, MISSOURI

LABORATORY REPORT


PAME 23 MEPONT A262

FINAL REPORT

FIGURE 17



2004 (1 30.23



MIO430 No. 24

Test Cup 6 Anodize - Electrofilm 9396

ST. LOUIS, MISSOURI

REPORT A262

LABORATORY REPORT

FINAL REPORT

FIGURE 18



()

M10436 No. 25



M10439 No. 26

Test Cup 7 Hardcoat - Everlube 620

ST. LOUIS, MISSOURI

LABORATORY REPORT

D4E- 264674

REVISED __

FIGURE 19





M1.0435 No. 27




· M10437 No. 28

Hardoost - Everlube 620

REVISED

LABORATORY REPORT

FINAL REPORT



M10547 No. 29



M10550 No. 30

Test Cup 8 Hardcoat - Molykote X-106


ST. LOUIS, MISSOURI

LABORATORY REPORT

PAGE 27
REPORT A262

FINAL REPORT

FIGURE 21



M10549 No. 31

unavailability of surface

Test Cup 8
Hardcoat - Molykote X-106

ST. LOUIS, MISSOURI

LABORATORY REPORT


FINAL REPORT

HEVISED

FIGURE 22



M10517 No. 33



M1.0434

Test Cup 9 Hardcoat - Electrofilm 5396


ST. LOUIS, MISSOURI

LABORATORY REPORT

PAGE 29 REPORT A262

FINAL REPOR


FIGURE 23



REVISED DEE-264678

M10433 No. 35

0



MO432 No. 35

Test Cup 9
Hardcoat - Bleetrofilm 9389

ST. LOUIS, MISSOURI LABORATORY REPORT REPORT

. REVISED DE- 264679


FINAL REPORT

FIGURE 24

Test Cup No. 10, Runs 1-4, was not available for photomecrographs



M10548



M10547 No. 6

Test Cup 11 Dow 17 - Molykote X-106

ST. LOUIS, MISSOURI

PAGE 31 REPORT A262

LABORATORY REPORT


FINAL REPORT

FIGURE 25

Test Cup No. 10, Runs 1-4, was not available for photomerographs



M10550 No. 7



N1.0549

No. t

Test Cup 11 Dow 17 - Molykote X-106

()

-

MCDONNELL ST. LOUIS, MISSOURI

LABORATORY REPORT

FINAL REPORT

REVISED . DE 264681 __

PIQURE 26



M10546 No. 9



M10543 No. 10

Test Cup 12 Dow 17 - Electrofilm 5396

ST. LOUIS, WISSOUTH

LABORATORY REPORT

PAGE 33: REPORT A252

FINAL REPORT

730008 27



REVISED _BE-264682

(

M10544 No. 11



M10548 No. 12

Test Cup 12
Dow 17 - Electrofilm 5396

ST. LOUIS, MISSOURI


PAGE 24 REPORT A262

REVISED

LABORATORY REPORT

PINAL REPORT

PTOURE 28



M9435 No. 13



M9434 No. 14

Test Cup 13 HAE Type II Everlube 620

ST. LOUIS, MISSOURI

LABORATORY REPORT

REVISED D4E-264684

FINAL REPORT

FIGURE 29



M9433 No. 15



No. 16 M9432

Test Cup 13 HAE Type II Everlube 620

ST, LOUIS, MISSOURI

PAGE 36 REPORT A262

REVISED D4E- 264685

LABORATORY REPORT

FINAL REPORT

FIGURE 30



M10544 No. 17



M10545 No. 18

Test Cup 14 BAB Type II Nolykote X-106

()

()

()


ST. Louis, MISSOURI

PAGE 37
REPORT A262

APPLISED DIE-264686 LABORATORY REPORT

FINAL REPORT

FIGURE 31



M10546

No. 19



M1.0543

No. 20

Test Cup 14 HAR Type II Molykote X-106

ST, LQUIS, MISSOURI

PAGE 38

REVISED DE SCHOOT

LABORATORY REPORT

FINAL REPORT

FIGURE 32





M10664 No. 21

M10662 No. 25

Test Cup 15 WAR Type II Electrofilm 539%

ST. LOUIS, MISSOURI

LABORATORY REPORT

PAGE 39 REPORT A262

FINAL REPORT

FIGURE 33



REVISEL DIE-264688

M10665 No. 23



M10663 No. 24

Test Cup 15 HAB Type II Electrofilm 5396

TITLE_	Evaluation of Dry F	ilm Lubricants	on Aluminum and
	Magnesium		
MEDIAYS	NY DA DEST. RESPONDENZ POR		W.S.
	/2 2.5 (PE ON ISM ☐ ON TPL NO ON PARTS FOR TEST NOT ROBUN		None

WORK REQUESTED

OBJECTIVE (MAKE PROPOSE OF TEST, WORK AND SATA REGULES.

1.0 OBJECT

To evaluate several dry film lubricants for wear life on aluminum and magnesium at room temperature and 250°F.

2.0 JUSTIFICATION

F6575-040

Existing vendor data recommends use of dry film lubricants on aluminum and magnesium. However, no testing has been conducted at MAC to substantiate the vendor data. Several recent production problems have indicated a need for test data to permit making reliable recommendations regarding lubrication of MAC products.

3.0 MATERIALS

- 3.1 7075-T6 aluminum Spec. QQ-A-282 Cond. T6 Size: 1.5"dia. rod x 12.0"
- 3.2 HM31A-F Magnesium Spec. AMS 4388 Size: 1.5"dia. rod x 8.0"
- 3.3 1130 Steel Spec. NHL-S-6778 Gend C Size: .377" x 1.00" x 10.0"
- 38 Redified NacMillan Tester for oscillatory motion and 250°F temperature.

4.0 SPECIMEN PREPARATION

4.1 Heat treat 4130 steel per P.S. 15013

- 4.2 Manufacture 10 test cups from 7075-T6 aluminum and 7 test cups from HM31a-F magnesium. The test cups will be manufactured per Figure I.
- 4.7 Manufacture Friders of the steel (Rc = 30) per Figure II.

REFERENCES OR ENCLOSURES
REY, B. CHARLE NO. REVISED AS PER MEMO MP 62-282

RAY C ADD ACTION

PAGE 41
REPORT A262

4.0 SPECIMEN PREPARATION (Continued)

4.4 Pretreatments (Sspecimens per pretreat).

4.4.1 Aluminum

- (a) Hard coat .002 inches thick per P.S. 13208.
- (b) Alodine per P.S. 13209.
- (c) Anodize per P.S. 13201.

4.4.2 Magnesium

- (a) Dow 17 per P.S. 13217. HAE WELLINS, 1950 W. 16, Mich (b) HAE per P.S. 13212: Brooks Perkins, 16, Mich
- 4.5 One specimen per pretreatment shall be coated with each of the following lubricants:
 - 4.5.1 Molykote X-106 per P.B. 841 of P.S. 1802.
 - 4.5.2 Electrofilm 99A applied at Dynacraft, St. Louis.
 - 4.5.3 Everlube 620 applied at Edco-Apex Testing Lab, St. Louis (bake: 2 hrs. @ 2250F).

5.0 TESTING

- 5.1 Test motion shall be oscillatory (210 cpm) resulting in (4) four testing surfaces per specimen, 2 tests at room temperature and 2 tests at 250°F.
- 5.2 Testing shall continue until the coefficient of friction (f) = 0.2, or until 50 hours has elapsed, whichever occurs first.
- 5.3 Loads shall be applied per MIL-L-25504.
- 5.4 Aluminum
 - 5.4.1 Test each specimen at room temperature with 10 lb. on the hanger on two (2) separate surfaces.
 - 5.4.1 Test each specimen at 250°F with 3 lb. on the hanger on two (2) separate surfaces.

5.5 Magnesium

- 5.5.1 Test each specimen at room temperature with 5 lb. on the hanger on two (2) separate surfaces.
- 5.5.2 Test each specimen at 250°F with 3 lb. on the hanger on two (2) separate surfaces.

Page 3 of 4

TEST REQUEST

PAGE 42
REPORT A262

NOTE: Sequence of testing shall be:

- koom temperature tests of hard coated aluminum with Molykote X-106 lubricant.
- 2. Room temperature test of anodized aluminum with Molykote X-106 lubricant.
- 3. Sequence unimportant after above testing is completed.

6.0 DATA REQUIRED

- 6.1 Report the number of cycles to failure (f = 0.2), or whether the specimen lasted 50 hours.
- 6.2 Photomicrographs of typical failures at 20X.


Revifi - Misalignment of the electrofilm wear

resting machine resulted in questionable data
Malars requested are for correcting alignment

& re-runs Approved S. Club 4 temp 4/30/62

Authorized & S. Sabb 5/3/62

perpint & Co



FIGURE

- I ECEPT AS NOTED IN T SYMBOL HOLD SURFACE TO LE PAS MICROINCHES
- A. CONCENTRICITY OF TAPERED DIA TO OD TO BE WITHIN . 0003 T. I.R
- 3 BREAK ALL SHARP CORNERS




FIGURE 11

THE 250 INCH DIMENSION SHALL BE PARALLEL TO

UNCLASSIFIED

UNCLASSIFIED